FLUKE®

General-Purpose Accessories

	743B	741B	712	713	714	715	716	717	787	87	51/52	16	123
Fluke 700Pxx Pressure Modules[1]	•	•					•	•					
BP7217 NiCd Battery Pack	•	•											
BE9005 Battery Eliminator	•	•											
BC7210 Battery Charger	•	•											
Fluke 700BCW Bar Code Wand	•												
Fluke 700BCA Bar Code Adapter	•												
Fluke 700TCI and TC2 Thermocouple Plug Kits	•	•			•								
80CJ-M and 80CK-M Mini-Connectors	•	•			•						•	•	
80PK Thermocouple Probes (all)	•	•			•						•	•	
Fluke 700-IV Current Shunt	•	•				•			•	•		•	•
Fluke 700PMP Pressure Pump	•	•		•			•	•					
Fluke 700PTP Pneumatic Test Pump	•	•		•			•	•					
Fluke 700HTP Hydraulic Test Pump	•	•		•			•	•					
Fluke 700PRV Pressure Relief Valve Kit	•	•		•			•	•					
Fluke 787CAL Calibration Kit									•				
80T-IR Infrared Probe	•	•				•			•	•		•	•
80PK-IR Infrared Probe	•	•			•						•	•	
80TK Thermocouple Module	•	•				•			•	•	•	•	•
80T-150U Universal Temperature Probe	•	•				•			•	•	•	•	•
TL20/22/24/26/28 Lead Sets	•	•	•	•		•	•	•	•	•		•	•
TL70A and Y8140A Lead Sets	•	•	•	•		•	•	•	•	•		•	
AC20 and AC80 Clips	•	•	•	•		•	•	•	•	•		•	•
TP20 Industrial Test Probes	•	•	•	•		•	•	•	•	•		•	
80i-400 AC Current Clamp	•	•							•	•			
i410 AC/DC Current Clamp	•	•				• 2	•	•	• 3	• 3		•	•
i1010 AC/DC Current Clamp	•	•				• 2	•	•	• 3	• 3		•	•
C10 Holster and C12A Case												•	
C25/C28/C90/C100/C800 Cases			•	•	•	•	•	•	•	•			
C781 Soft Carrying Case	•	•											
C789 Soft Carrying Case	•	•											•
C700 Hard Carrying Case	•	•											
C120 and C125 Case													•
80K-6 and 80K-40 High Voltage Probes	•	•							•	•			•
83RF and 85RF High Frequency Probes	•	•							•	•		•	•
PV350 Pressure Vacuum Module	•	•				•			•	•		•	•
Fiber Optic Meter (FOM)	•	•				•			•	•		•	•

[1] Ask for Application Note B0300
[2] DC current only
[3] 20A ac minimum

Fluke. *Keeping your world up and running.*

Fluke Corporation
PO Box 9090, Everett, WA USA 98206

Fluke Europe B.V.
PO Box 1186, 5602 BD, Eindhoven, The Netherlands

For more information call:
U.S.A. (800) 443-5853 or Fax (425) 356-5116
Europe (31 40) 2 678 200 or Fax (31 40) 2 678 222
Canada (905) 890-7600 or Fax (905) 890-6866
Other countries (425) 356-5500 or Fax (425) 356-5116
Internet: http://www.fluke.com

©1998 Fluke Corporation. All rights reserved.
Printed in U.S.A. 4/98 A0602NEN Rev A

Printed on recycled paper.